

## Cockpit crew status

- **90 days currency**

According to OPS 1.970 a pilot should carry out **3 take-offs and 3 landings in the previous 90 days** as pilot flying in an aeroplane, or in a flight simulator of the same type/class.

## IMPORTANT INFORMATION !

**'90 days currency' feature will work only when 'Journey Log' has been added to Leon and the field 'Flown by' has been filled in**

An example below will explain how this feature works.

Crew **TAR** has carried **3 take-offs and 3 landings in previous 90 days on 2 types of aircraft.**



Go to Crew > Duties section - right next to pilot's code there is a status-dot. Hover the mouse over the dot to get the information displayed in the pop-up window. In case of crew **TAR** it shows, that **51** days left to expire '90 days currency' for aircraft **G450** and **81** days for aircraft **H750** - here is how it was calculated:

### G450

- the latest take-off/landing was on **01-09**
- 90 days expiration period will be on **29-11**
- the date of checking is **10-10**
- between 10-10 and 29-11 there is **51 days** (including the 10th of October and the 29th of November).

### H750

- the latest take-off/landing was on **01-10**
- 90 days expiration period will be on **29-12**
- the date of checking is **10-10**
- between 10-10 and 29-12 there is **81 days** (including the 10th of October and the 29th of December).



If a pilot **has not carried 3 take-offs and landings within 90 days**, when hovering the mouse over the status-dot, the information will be displayed as '**0**' days left. If the number between the latest take-off/landing and the current date (date of checking) is **lower than 30** - the dot will become **orange**. The same applies to **night landing** status.

**The colour of the status-dot depends on the settings of the filter. Section 'Cockpit crew status' has 3 checkboxes to be ticked: 90 days currency, night landings and endorsements required for dispatch - unticked option/options will not affect the colour of the status-dot**

From:  
<https://wiki.leonsoftware.com/> - Leonsoftware Wiki

Permanent link:  
<https://wiki.leonsoftware.com/updates/we-have-added-a-new-option-to-monitor-90-days-currency-for-cockpit-crew>

Last update: **2016/08/30 13:06**

